

REJECTIONS:

- (1) When an inspection is rejected, the contractor receives an email notice from RAP. The contractor must **respond to the notice within 3 business days** stating if the property will be re-inspected or not. *If we do not hear from you within 3 business days, the rejection will stand.*
- (2) The re-inspection must be **scheduled within 15 days** of the rejection notice from RAP. After the re-inspection is scheduled, send an email to REACReverseAuctionProgram@hud.gov with the new date and time so that the inspection can be re-set in the system.
- (3) The re-inspection must occur within the period of performance or within a reasonable timeframe, generally 30 days from the date of the notice of rejection.
- (4) If the 30 days is beyond the period of performance, send an extension request to REACReverseAuctionProgram@hud.gov as soon as the re-inspection is scheduled.